

Radiant Heater RH600 Technical Service Bulletin # 6

Re: List of useable Logic PCBs

Date: October 16, 2001

Reference Doc: N/A

Reason: For your information the list of useable and not useable Logic PCBs.

Please note that all devices RH600 have been updated during the actions according to TSB RH600 # 5 with updated and useable

Logic PCBs.

Solution: Table of Logic PCBs and status:

P/N Logic PCB	Status
8306101 / SE8306101	Not useable
2M22408 / SE2M22408	Useable
2M22409 / SE2M22409	Useable
2M22383 / SE2M22383	Useable

Note: If a Logic PCB with a status "not useable" is found this PCB must

be replaced with a Logic PCB with a status "useable".

Devices affected: All devices Radiant Heater RH600

When: Next repair or when a Logic PCB with a status "not useable" is

found.

Reporting: Yes, by fax to Regulatory Affairs

Additional Info: N/A

Cost: N/A

Ordering Info: Logic PCB P/N 2M22383

Distribution: Dräger Service Personnel and Authorized Service Organizations.

6134.0 Radiant Heater RH600 TSB No. 6 October 2001 1/2



If you have any questions, please contact Technical Support by phone at 1-800-543-5047 or by fax at 1-215-721-5789.

Dräger Medical, Inc. Technical Product Manager

6134.0 Radiant Heater RH600 TSB No. 6 October 2001 2/2